

SOUTHERN CRUSHED CONCRETE INC.

May 16, 2002


To: Whom It May Concern:

Southern Crushed Concrete, Inc. certifies that our 3 x 5 inch – Recycled Crushed Concrete Bull Rock will meet the Harris County Flood Control Specification 02378 – Rip Rap Granular Fill Material. Please see the attached Sieve Analysis. If you need any addition Information, please let me know.

Sincerely,



James R. Miller



14329 Chrisman Road • Houston, Texas 77039
(281) 987-8789 • FAX (281) 987-8791
Equal Opportunity Employer





**Hercules Engineering & Testing
Services**

A Division of **PSI** Information
To Build On
Engineering • Consulting • Testing

REPORT OF SIEVE ANALYSIS

TESTED FOR: Mr. Jim Miller
Southern Crushed Concrete
14329 Chrisman Road
Houston, Tx 77039

PROJECT: Southern Crushed Concrete
Miscellaneous Testing
Houston, Texas

DATE: September 06, 2001

OUR REPORT NO.: 206-80010-371

REMARKS: On September 6, 2001 a representative of Hercules/PSI arrived at Southern Crushed Concrete's Genoa Red Bluff Plant to sample 3x5 inch Recycled Crushed Concrete Bull Rock for a field sieve analysis. The sieve analysis was performed on 706.25 lbs. of material using hand sieving techniques in general accordance with ASTM C136-96A. The results of the testing are as follows:

<u>Sieve Size</u>	<u>Sample Results, % Passing</u>	<u>HCFCD Sect. 02378 Part 2.2.B.1 % Passing</u>
5"	96 *	100
4"	84	N/A
3"	9 *	0

* - Does not meet HCFCD Section 02378 Grading Specifications.

The results apply only to the specific sample tested and may not be representative of the entire stockpile. If there are any questions concerning this report or if we can provide any additional information, please contact us at your convenience.

Technician: S. Capuyan, NICET III
Time: 7:00 am - 2:24 pm
Technician: J. Vargas
Time: 7:00 am - 1:00 pm

Respectfully submitted,
Hercules/PSI

Ronald E. Ortwerth, P.E.
Senior Vice President

cc: (1) Backup; (3) Southern Crushed Concrete-Jim Miller



REPORT OF SIEVE ANALYSIS

TESTED FOR: Mr. Jim Miller
Southern Crushed Concrete
14329 Chrisman Road
Houston, Tx 77039

PROJECT: Southern Crushed Concrete
Miscellaneous Testing
Houston, Texas

DATE: September 06, 2001

OUR REPORT NO.: 206-80010-371

REMARKS: On September 6, 2001 a representative of Hercules/PSI arrived at Southern Crushed Concrete's Genoa Red Bluff Plant to sample 3x5 inch Recycled Crushed Concrete Bull Rock for a field sieve analysis. The sieve analysis was performed on 706.25 lbs. of material using hand sieving techniques in general accordance with ASTM C136-96A. The results of the testing are as follows:

<u>Sieve Size</u>	<u>Sample Results, % Passing</u>	<u>HCFCD Sect. 02378 Part 2.2.B.1 % Passing</u>
5"	96 *	100
4"	84	N/A
3"	9 *	0

* - Does not meet HCFCD Section 02378 Grading Specifications.

The results apply only to the specific sample tested and may not be representative of the entire stockpile. If there are any questions concerning this report or if we can provide any additional information, please contact us at your convenience.

Technician: S. Capuyan, NICET III
Time: 7:00 am - 2:24 pm
Technician: J. Vargas
Time: 7:00 am - 1:00 pm

Respectfully submitted,
Hercules/PSI

Ronald E. Ortwerth, P.E.
Senior Vice President

cc: (1) Backup; (3) Southern Crushed Concrete-Jim Miller



REPORT OF SIEVE ANALYSIS

TESTED FOR: Mr. Jim Miller
Southern Crushed Concrete
14329 Chrisman Road
Houston, Tx 77039

PROJECT: Southern Crushed Concrete
Miscellaneous Testing
Houston, Texas

DATE: September 06, 2001

OUR REPORT NO.: 206-80010-371

REMARKS: On September 6, 2001 a representative of Hercules/PSI arrived at Southern Crushed Concrete's Genoa Red Bluff Plant to sample 3x5 inch Recycled Crushed Concrete Bull Rock for a field sieve analysis. The sieve analysis was performed on 706.25 lbs. of material using hand sieving techniques in general accordance with ASTM C136-96A. The results of the testing are as follows:


<u>Sieve Size</u>	<u>Sample Results, % Passing</u>	<u>HCFCD Sect. 02378 Part 2.2.B.1 % Passing</u>
5"	96 *	100
4"	84	N/A
3"	9 *	0

* - Does not meet HCFCD Section 02378 Grading Specifications.


The results apply only to the specific sample tested and may not be representative of the entire stockpile. If there are any questions concerning this report or if we can provide any additional information, please contact us at your convenience.

Technician: S. Capuyan, NICET III
Time: 7:00 am - 2:24 pm
Technician: J. Vargas
Time: 7:00 am - 1:00 pm

Respectfully submitted,
Hercules/PSI



Ronald E. Ortwerth, P.E.
Senior Vice President



cc: (1) Backup; (3) Southern Crushed Concrete-Jim Miller

